

DIRECT CLUTCH Services

Clutch Specialists

Shanked bolt PDF

*Special note: Many of the older flywheels do not run modern style dowels. Instead these units required a bolt with a specific shank. Failing to run these correct shank bolts will result in an imbalance, by allowing the clutch cover to move off centre and potential clutch explosion at higher RPM! Very dangerous!

Pic 1: the shanked hole can be seen in this flywheel....and the corresponding shanked bolt in pic 2:



This ensures complete accuracy when fitting the old non doweled clutch covers.

Direct Clutch Services: **39 Crosby Road Albion Queensland Australia 4010**

Ph: **07 3862 2680**

sales@directclutch.com.au    www.directclutch.com.au